

Access and Language Options





Login/Register



About Us Places to Go How to use DisabledGo News and Blog Home Site Map

You Are Here: Home > Places to Go > Venue



Holiday Inn Rotherham - Sheffield M1,



Guide Last Updated: 13/10/2017









Explain These Icons

Add To My Trip

View the Access Guide

West Bawtry Road, Rotherham, S60 2XL 0871 510 1376

https://www.ihg.com/holidayinn/hotels/gb/en/rotherham/emart/hoteldetail

[] CANKLOW

Google &

Something Changed? Click Here

Venue Reviews

Average Rating:

Review this Venue

Map data ©2017 Google

Access Guide

Hotel Introduction Collapse -

Related Access Guide(s)

Hotel Information

Collapse -

• For the Holiday Inn Rotherham - Sheffield M1, Jct.33 - Leisure Facilities DisabledGo access guide please click here (new tab).

Collapse -

- The hotel has its own parking facilities.
- This hotel has its own restaurant located on the ground floor.
- Conference/meeting facilities are available.
- The conference/meeting facilities are located on the mezzanine floor and the third floor.

Room Information Collapse -

- The hotel has 197 rooms in total.
- There is an/are accessible room(s) within the hotel.
- The accessible room(s) is/are located on the ground floor.
- The hotel has 2 accessible room(s) with accessible ensuite facilities.

ble room(s) with a wet room/wheel in shower. Cookie Policy

- There is an/are adjoining room(s) available for the accessible room(s).
- There is a/are standard room(s) available on the ground floor.
- There is an/are adjoining room(s) available for the standard room(s).
- Rooms on other floors are accessed via stairs or lift.

Auxiliary Aids Collapse -

- Vibrating pillows with flashing beacons are available on request.
- Bed raisers are not available on request.
- Bath mats are available on request.
- All televisions have subtitles available.

Getting Here Collapse -

By Road Collapse -

- This hotel is located on the outskirts of Rotherham, just off Junction 33 of the M1. The hotel is located on the A630.
- This hotel has a car park which is free for all users.

By Bus Collapse -

- There is not a bus stop within 150 metres of the hotel.
- The nearest bus stop is located on the opposite side of the A630, approximately 350 metres from the hotel.
- For more information on buses in South Yorkshire please click here (opens new tab).

By Train Collapse -

- The nearest Railway Station is Rotherham.
- Rotherham Station is situated in the centre of Rotherham, located approximately 4km from the hotel. There are bus and taxi routes
 to the hotel from the station.
- For more information on National Rail please click here (opens new tab).

Getting Help and Assistance Collapse -

- There is a member of staff available for help and assistance.
- Staff receive disability awareness/equality training.
- Staff receive deaf awareness training.
- There is not a member of staff trained in British Sign Language.
- British Sign Language interpreters cannot be provided on request.
- There is an assistance dog toilet or toileting area at the venue/near by.
- The assistance dog toilet or toileting area is located at the rear of the hotel.
- Water bowls for assistance dogs are available.
- There are not mobility aids available.

Parking Collapse -

Parking Collapse -

Cookie Policy :s own parking facilities.

- The car park is located off West Bawtry Road.
- The car park type is open air/surface.
- The car park does not have a height restriction barrier.
- The car park does not have a barrier control system.
- The car park surface is tarmac.
- There is a/are Blue Badge parking bay(s) available.
- The Blue Badge bay(s) is/are clearly marked.
- There is/are 5 designated Blue Badge parking bay(s) within the car park.
- The dimensions of the designated Blue Badge parking bay(s) surveyed are 490cm x 490cm (16ft 1in x 16ft 1in).
- There is not a 120cm hatched zone around the Blue Badge parking bay(s).
- The dimensions of other designated Blue Badge parking bay(s) vary in size.
- Parking spaces for Blue Badge holders do not need to be booked in advance.
- Clearly marked/signposted parent and child parking bays are not available.
- All parking spaces are provided on a first come first served basis.



• There are not parking charges for the car park.

Access from the Car Park

- The route from the car park to the entrance is accessible to a wheelchair user with assistance.
- Assistance may be required because there is/are slopes/ramps.
- The entrance is clearly visible from the car park.
- The surface on the approach to the entrance is tarmac.
- There is not a road to cross between the car park and the entrance.
- There is no tactile paving on dropped kerbs between the car park and the entrance.

Drop-off Point(s) Collapse -

• There is not a/are not clearly marked drop-off point(s).







Collapse -

Entrance

Outside Access (Hotel Entrance)

Collapse -

Collapse -

- This information is for the entrance located at the front of the hotel.
- The entrance area/door is clearly signed.
- There is ramped/sloped or stepped access at this





- There is a canopy or recess which provides weather protection at this entrance.
- The entrance door(s) does not/do not contrast visually with its immediate surroundings.
- The main door(s) open(s) automatically.
- The door(s) is/are double width.
- The width of the door opening is 137cm.
- There is a second set of doors.
- The door(s) open(s) automatically.
- The door(s) is/are double width.
- The width of the door opening is 125cm.

Ramp/Slope

Collapse -

- The ramp/slope is located to the right as you face the entrance.
- The gradient of the ramp/slope is slight.
- The ramp/slope is permanent.
- There is a level landing at the top of the ramp/slope.
- There is a/are handrail(s) at the ramp.
- The handrail(s) is/are on both sides going up.
- The ramp/slope does bypass the step(s).

Step(s)

Collapse -

- The step(s) is/are located in front of the entrance.
- There is/are 5 step(s).
- The step(s) is/are not clearly marked.
- The height of the step(s) is/are between 15cm and 18cm.
- The going of the step(s) is/are between 30cm and 45cm.
- There is a/are handrail(s) at the step(s).
- The handrail(s) is/are on both sides going up.
- Handrails are not at the recommended height (90cm-100cm).
- Handrails do cover the flight of stairs throughout its length.
- Handrails are not easy to grip.
- Handrails do not extend horizontally beyond the first and last steps.



Reception Collapse -

Reception

Collapse -

- The reception point is located to the left as you enter the hotel entrance.
- The reception point is approximately 4m (4yd 1ft) from the hotel entrance.
- The reception area/desk is clearly visible from the entrance.

Cookie Policy

ess to the reception point.





- There is a clear unobstructed route to the reception point.
- There are no windows, TVs, glazed screens or mirrors behind the reception point which could adversely affect the ability of someone to lip read.
- The reception counter is not placed in front of a background which is patterned.
- The lighting levels at the reception point are good.
- The height of the reception counter is high (110cm+).
- There is sufficient space to write or sign documents on the counter.
- There is a lowered section of the counter.
- The lowered section of the counter is not at the recommended height of 76cm.
- There is sufficient space to write or sign documents on the lowered section of the counter.
- There is a clear knee recess beneath the lowered section of the counter.
- The clear knee recess has the recommended dimensions of 70cm (height) x 50cm (depth).
- The counter is staffed.
- There is not a hearing assistance system at the reception point.
- Signs and universally accepted symbols or pictograms, indicating lifts, stairs, WCs, circulation routes and other parts of the building are provided in the reception area.
- The type of flooring in the reception area is laminate.

Reception Waiting Area

Collapse -

- There is a waiting area close to the reception point.
- Access to the waiting area is unobstructed.
- There is a mixture of seating with and without armrests.
- There is sufficient space for a wheelchair user to use the waiting area.



Getting Around Collapse -

Access

Collapse -

• There is step free access throughout the building.

Circulation

Collapse -

- There are doors in corridors/walkways which have to be opened manually.
- The type of flooring in corridors/walkways is carpet.
- There is some flooring in corridors/walkways which includes patterns or colours which could be confusing or look like steps or holes to some people.
- There is good colour contrast between the walls and floor in the majority of corridors/walkways.
- The lighting levels are good.

Cookie Policy

/levels is via stairs and lift.





Signage

Collapse -

- Wayfinding signage is provided.
- The colour, design and typeface of signs is consistent throughout the building.

Audio

Collapse -

- This venue does play background music in public areas.
- Music is played in the reception area, bar area and throughout the leisure areas.
- There is not a hearing assistance system in the public areas of the building.

Eating and Drinking (Bar)

Collapse -

- The following information is for the bar.
- The bar is located to the right as you enter the hotel entrance.
- There is step free access to the bar.
- Full table service is not available.
- Food and/or drinks are ordered from the service counter.
- Food and/or drinks can be brought to the table.
- The height of the service counter is high (110cm+).
- There is not a lowered section of the counter.
- There is not a hearing assistance system.
- There is step free access within the bar.
- There is ample room for a wheelchair user to manoeuvre.
- This area does play background music.
- The type of flooring in this area is carpet, tiles and laminate.
- Some tables are permanently fixed.
- Some chairs are permanently fixed.
- · Some chairs have armrests on both sides.
- The nearest table is approximately 2m from the entrance/opening.
- The nearest table is approximately 2m from the till/counter.
- The distance between the floor and the lowest table is 60cm.
- The distance between the floor and the highest table is 99cm.
- Plastic/takeaway cups are available.
- Plastic/takeaway cutlery is available.
- Drinking straws are available.
- There are hand held menus and wall menus available.
- Menus are not available in Braille.
- Menus are not available in large print.
- Picture menus are not available.
- Menus are clearly written.
- Menus are presented in contrasting colours.
- The type of food served here is hot and cold meals and snacks.

Cookie Policy

od.













Eating and Drinking (The Cow on the Hill - Steak and Grill)

Collapse -

- The following information is for the restaurant.
- The restaurant is located to the right as you enter the hotel entrance, to the side of the bar.
- There is step free access to the restaurant.
- Full table service is available.
- There is not a hearing assistance system.
- There is step free access within the restaurant.
- There is ample room for a wheelchair user to manoeuvre.
- This area does play background music.
- The type of flooring in this area is wood.
- Some tables are permanently fixed.
- Some chairs are permanently fixed.
- No chairs have armrests on both sides.
- The nearest table is approximately 1m from the entrance/opening.
- The standard height for tables is 70cm.
- Plastic/takeaway cups are available.
- Plastic/takeaway cutlery is available.
- Drinking straws are available.
- There are hand held menus and wall menus available.
- Menus are not available in Braille.
- Menus are not available in large print.
- Picture menus are not available.
- Menus are clearly written.
- Menus are presented in contrasting colours.
- The lighting levels are good.













Accessible Room(s) (Rooms 1 and 3)

Collapse -

Accessible Room Information

Collapse -

- The details in this section relates to the accessible room(s) with a wet room/wheel in shower.
- This type of accessible room is located on the ground floor.
- There is step free access to this type of accessible room.
- All accessible rooms of this type have similar specifications.
- The ensuite transfer space for the accessible rooms varies from left to right.
- Guests need to open a door between the entrance and the room(s).
- The narrowest width of the corridor leading to the room surveyed was 150cm.

Bedroom Features

Collapse -

 The accessible room surveyed is located on the ground Cookie Policy













- The accessible room surveyed at the time of the visit was Room 1.
- There is step free access to the accessible room surveyed.
- There is numbered signage on or near the accessible room door.
- The door is key card activated.
- The width of the door is 76cm (2ft 6in).
- There are lowered spy holes available.
- The bed type is double.
- The bed height is not adjustable.
- The height of the bed is 59cm (1ft 11in).
- The measurement between the bed base and floor is 12cm (5in).
- The bed is moveable.
- The room does not have an unobstructed minimum turning space of 150cm x 150cm next to the bed.
- The desk is not height adjustable.
- The desk knee recess has the recommended dimensions of 70cm (height) x 50cm (depth).
- The room surveyed had an armchair.
- Wardrobes have not been adapted to allow use from a seated position.
- Light switches are not between 75cm and 120cm (4ft) from floor level.
- Electric sockets are between 40cm and 100cm (4ft) from floor level.
- The window control type(s) for the room is a/are standard lever(s).
- There is an emergency alarm in the room.
- The emergency pull cord alarm is out of reach (higher than 10cm (4") from floor).
- The emergency alarm rings to reception.
- There is not a flashing fire alarm beacon within the room.
- The type of flooring is carpet.
- The coat hooks are 140cm high. The light switches are between 60cm and 120cm from floor level.

Ensuite Facilities

Collapse -

- The ensuite door opens outwards.
- The door weight is light.
- The door is locked by a twist lock.
- The width of the door to the ensuite is 85cm (2ft 9in).
- The dimensions of the ensuite are 170cm x 240cm (5ft 7in x 7ft 10in).
- The ensuite does have an unobstructed minimum turning space of 150cm x 150cm in front of the toilet seat.
- The ensuite has a non slip floor.
- There is an emergency alarm within the ensuite.
- The emergency pull cord alarm is out of reach (higher than 10cm (4") from floor).

Cookie Policy

rings to reception.

- There is not a flashing fire alarm beacon within the ensuite.
- Disposal facilities are available.
- There is a/are pedal waste paper bin disposal units.
- There is a mirror.
- The mirror is not placed at a lower level or at an angle for ease of use.
- There is not a shelf immediately next to or behind the toilet.
- There is a wash basin.
- The wash basin cannot be reached from seated on the toilet.
- The wash basin is not placed higher than 74cm (2ft 5in).
- The height of the wash basin is 70cm.
- There are vertical wall-mounted grab rails on both sides of the wash basin.
- The tap type is lever.
- There is a mixer tap.
- There is a soap dispenser.
- The soap dispenser cannot be reached from seated on the toilet.

Toilet Details

Collapse -

- The height of the toilet seat above floor level is 46cm (1ft 6in).
- The toilet has a wall which acts as a backrest.
- There is a lateral transfer space.
- As you face the toilet pan the transfer space is on both sides.
- The lateral transfer space on the left is 120cm.
- The lateral transfer space on the right is 80cm.
- There is a flush on the transfer side.
- There is a spatula type lever flush.
- There is a dropdown rail on the transfer side.
- There is not a/are not wall-mounted grab rail(s) available.
- There is a toilet roll holder.
- The toilet roll holder can be reached from seated on the toilet.
- The toilet roll holder is not placed higher than 100cm (3ft 3in).

Shower Details

Collapse -

- The ensuite has a wheel in shower.
- The shower head is height adjustable.
- The shower control type is lever.
- A shower chair is available.
- The height of the flip down/tip up or fixed seat is 43cm (1ft 5in).
- There is a/are wall-mounted grab rail(s) available for the Cookie Policy

- Horizontal and/or dropdown rails are available on both sides of the shower seat.
- There is a single vertical grab rail to assist standing users.

Colour Contrast and Lighting

Collapse -

- The colour contrast between the external hotel room door and wall is good.
- The colour contrast between the internal hotel room door and wall is good.
- The colour contrast between the hotel room walls and floor is good.
- The colour contrast between the external ensuite door and wall is good.
- The colour contrast between the internal ensuite door and wall is poor.
- The colour contrast between the ensuite walls and floor is fair.
- The colour contrast between the drop down rail(s) and wall is good.
- The contrast between the wash basin wall-mounted grab rail(s) and wall is good.
- The colour contrast between the shower wall-mounted grab rails and wall is fair.
- The toilet seat colour contrast is poor.
- The lighting levels in the room are good.
- The lighting levels in the ensuite are good.

Standard Room(s) (Room 220)

Collapse -

Bedroom Features

Collapse -

- The room surveyed is located on the second floor.
- The room surveyed at the time of the visit was Room 220.
- There is step free access to the room surveyed, via lift.
- There is pictorial signage on or near the room door.
- The width of the door is 76cm (2ft 6in).
- The bed type is double.
- The height of the bed is 58cm (1ft 11in).
- The measurement between the bed base and floor is 12cm (5in).
- Light switches are within 120cm (3ft 11in) from floor level.
- There is not an emergency alarm in the room.
- There is not a flashing fire alarm beacon within the room.
- The type of facilities within the ensuite include; a toilet, a wash basin and a bath.
- The ensuite door opens inwards.
- The width of the door to the ensuite is 66cm (2ft 2in).
- There is not an emergency alarm within the ensuite.
- There is not a flashing fire alarm beacon within the

Cookie Policy

urn.









• There is not a mixer tap.

Colour Contrast and Lighting

Collapse -

- The colour contrast between the external hotel room door and wall is good.
- The colour contrast between the internal hotel room door and wall is good.
- The colour contrast between the hotel room walls and floor is good.
- The colour contrast between the external ensuite door and wall is good.
- The colour contrast between the internal ensuite door and wall is good.
- The colour contrast between the walls and floor in the ensuite is good.
- The lighting levels in the room are good.
- The lighting levels in the ensuite are good.

Standard Room(s) (Executive Room 214)

Collapse -

Bedroom Features

Collapse -

- The room surveyed is located on the second floor.
- The room surveyed at the time of the visit was Room 214.
- There is step free access to the room surveyed, via lift.
- There is numbered signage on or near the room door.
- The width of the door is 76cm (2ft 6in).
- The bed type is double.
- The height of the bed is 60cm (1ft 12in).
- The measurement between the bed base and floor is 12cm (5in).
- Light switches are within 120cm (3ft 11in) from floor level.
- There is not an emergency alarm in the room.
- There is not a flashing fire alarm beacon within the room.
- The type of facilities within the ensuite include; a toilet, a wash basin and a bath.
- The ensuite door opens inwards.
- The width of the door to the ensuite is 66cm (2ft 2in).
- There is not an emergency alarm within the ensuite.
- There is not a flashing fire alarm beacon within the ensuite.
- The tap type is lever.
- There is a mixer tap.

Colour Contrast and Lighting

Collapse -

- The colour contrast between the external hotel room door and wall is good.
- The colour contrast between the internal hotel room door











- The colour contrast between the hotel room walls and floor is good.
- The colour contrast between the external ensuite door and wall is good.
- The colour contrast between the internal ensuite door and wall is good.
- The colour contrast between the walls and floor in the ensuite is good.
- The lighting levels in the room are good.
- The lighting levels in the ensuite are good.

Other Floors Collapse -

Stairs

Collapse -

- Stairs can be used to access other floors.
- The stairs are for public use.
- The stairs are located ahead as you enter the hotel entrance.
- The stairs are approximately 7m from the hotel entrance.
- The stairs are clearly visible from the entrance.
- There are manual, heavy, double doors to enter the stairwell on the ground floor.
- The floors which are accessible by stairs are G, M, 1, 2 and 3
- There are 15+ steps between floors.
- The height of the step(s) is/are between the recommended 15cm and 18cm.
- The going of the step(s) is/are between the recommended 30cm and 45cm.
- The steps are clearly marked.
- There is a/are handrail(s) at the step(s).
- The steps have a handrail on both sides.
- Handrails are at the recommended height (90cm-100cm).
- Handrails do cover the flight of stairs throughout its length.
- Handrails are not easy to grip.
- Handrails do not extend horizontally beyond the first and last steps.
- There is a landing.
- Clear signs indicating the facilities on each floor are provided on landings.
- The lighting levels at the steps are good.







Lift Collapse -

- There is a lift for public use.
- The lift is located to the right of the reception area.
- Signs indicating the location of the lift are clearly visible from the entrance.

Cookie Policy

2m (13yd 4in) from the hotel entrance.

- The lift is a standard lift.
- A member of staff does not need to be notified for use of the lift.
- The floors which are accessible by this lift are G, M, 1, 2 and 3.
- Clear signs indicating the facilities on each floor are provided on lift lobby landings.
- There is a clear level manoeuvring space of 150cm × 150cm in front of the lift.
- Lift doors do not contrast visually with lift lobby walls.
- The external controls for the lift are within 90cm 110cm from the floor.
- The colour contrast between the external lift controls and the control plate is poor.
- The colour contrast between the external lift control plate and the wall is poor.
- The clear door width is 80cm (2ft 7in).
- The dimensions of the lift are 110cm x 140cm (3ft 7in x 4ft 7in).
- There are separate entry and exit doors in the lift.
- There is not a mirror to aid reversing out of the lift.
- There is a list of floor services available within the lift.
- The lift does have a visual floor indicator.
- The lift does have an audible announcer.
- The controls for the lift are within 90cm 120cm from the floor.
- There is not a hearing loop system.
- The lift does not have Braille markings.
- The lift does have tactile markings.
- The lighting levels in the lift are good.
- There is a/are similar lift(s) available.



Collapse -

Conference / Meeting Facilities (Peter Elliot Suite)

- Conference/meeting facilities are available.
- The conference/meeting facilities are located on the mezzanine floor, ahead as you exit the lift.
- There is step free access to the conference/meeting facilities, via lift.
- The door opening width(s) is/are 75cm+ for the room(s).
- There is not a hearing assistance system for the room(s).
- There are no chairs with armrests on both sides within the room(s).
- There is sufficient space for a wheelchair user to manoeuvre within the room(s).
- The lighting levels in the room(s) are good.

Comments

Collapse -

 The layout of the room varies depending on the function or event.







Conference / Meeting Facilities (Donna Harley Suite)

Collapse -

Conference/meeting facilities are available.
 Cookie Policy

- The conference/meeting facilities are located on the mezzanine floor, to the left as you exit the lift.
- There is step free access to the conference/meeting facilities, via lift.
- The door opening width(s) is/are 75cm+ for the room(s).
- There is not a hearing assistance system for the room(s).
- There are no chairs with armrests on both sides within the room(s).
- There is sufficient space for a wheelchair user to manoeuvre within the room(s).
- The lighting levels in the room(s) are good.

Comments

Collapse -

- The height of the majority of tables from the floor is 70cm.
- The layout of the room varies depending on the function or event.









Conference / Meeting Facilities (Seb Coe Suite)

- Conference/meeting facilities are available.
- The conference/meeting facilities are located on the mezzanine floor, to the right as you exit the lift.
- There is step free access to the conference/meeting facilities, via lift.
- The door opening width(s) is/are 75cm+ for the room(s).
- There is not a hearing assistance system for the room(s).
- There are no chairs with armrests on both sides within the room(s).
- There is sufficient space for a wheelchair user to manoeuvre within the room(s).
- The lighting levels in the room(s) are good.

Comments

Collapse -

- The height of the lowest table from the floor is 70cm.
- The height of the highest table from the floor is 75cm.
- The layout of the room varies depending on the function or event.











Accessible Toilet(s) (Ground Floor)

• There is an/are accessible toilet(s) for public use.

Location and Access

Collapse -

- The accessible toilet surveyed is not for the sole use of disabled people.
- This accessible toilet is located on the ground floor, at the rear of the bar.
- This accessible toilet is approximately 15m (16yd 1ft) from the hotel entrance.
- There is step free access to the accessible toilet.

Cookie Policy





Collapse -

Features and Dimensions

Collapse -

- This is a shared toilet.
- A key is not required for the accessible toilet.
- There is pictorial signage on or near the toilet door.
- The door opens outwards.
- The door is light.
- The door is locked by a twist lock.
- The width of the accessible toilet door is 87cm (2ft 10in).
- The dimensions of the accessible toilet are 163cm x 175cm (5ft 4in x 5ft 9in).
- The accessible toilet does not have an unobstructed minimum turning space of 150cm x 150cm.
- The toilet has a non slip floor.
- There is a lateral transfer space.
- As you face the toilet pan the transfer space is on the right.
- The lateral transfer space is 89cm (2ft 11in).
- There is a flush on the transfer side.
- There is not a spatula type lever flush.
- There is a dropdown rail on the transfer side.
- There is an emergency alarm.
- The emergency pull cord alarm is not fully functional.
- The alarm was out of reach (higher than 10cm (4") from floor) when surveyed.
- There is a flashing fire alarm beacon within the toilet.
- Disposal facilities are available in the toilet.
- There is a/are female sanitary and open waste paper bin disposal units.
- There is not a/are not coat hook(s).

Position of Fixtures

Collapse -

- There is a/are wall-mounted grab rail(s) available.
- As you face the toilet the wall-mounted grab rail(s) is/are on the left.
- There is not a vertical wall-mounted grab rail on the transfer side.
- There is a horizontal wall-mounted grab rail on the opposite side of the seat to the transfer space.
- There is a mirror.
- The mirror is not placed at a lower level or at an angle for ease of use.
- There is a shelf next to the toilet.
- The shelf is not between 90cm and 100cm.
- The toilet has a covered cistern.
- The height of the toilet seat above floor level is 40cm (1ft 4in).
- There is a toilet roll holder.
- The toilet roll holder can be reached from seated on the

- The toilet roll holder is not placed higher than 100cm (3ft 3in).
- There is a wash basin.
- The wash basin cannot be reached from seated on the toilet
- The wash basin is placed higher than 74cm (2ft 5in).
- The height of the wash basin is 78cm (2ft 7in).
- There is a vertical wall-mounted grab rail on the right hand side of the wash basin.
- The wash basin tap type is lever.
- There is not a mixer tap.
- There is a soap dispenser.
- The soap dispenser cannot be reached from seated on the toilet.
- The height of the soap dispenser is 80cm.
- There is a towel dispenser.
- The towel dispenser cannot be reached from seated on the toilet
- The towel dispenser is placed higher than 100cm (3ft 3in).
- The height of the towel dispenser is 130cm (4ft 3in).
- There is not a hand dryer.

Colour Contrast and Lighting

Collapse -

- The contrast between the external door and wall is good.
- The contrast between the internal door and wall is poor.
- The contrast between the dropdown rail(s) and wall is poor.
- The contrast between the wall-mounted grab rail(s) and wall is poor.
- The toilet seat colour contrast is poor.
- The contrast between the walls and floor is good.
- The lighting levels are good.

Baby Changing Facilities

Collapse -

- Baby changing facilities are located within the accessible toilet.
- The baby change table is not set against the wall, permanently fixed at 75cm from the floor.
- The baby change table is not height adjustable.
- The height of the baby change table once extended is 93cm (3ft 1in).

Accessible Toilet(s) (Mezzanine Floor)

Collapse -

• There is an/are accessible toilet(s) for public use.

Location and Access

Collapse -

• The accessible toilet surveyed is not for the sole use of

- This accessible toilet is located on the mezzanine floor, ahead as you exit the lift.
- This accessible toilet is approximately 5m (5yd 1ft) from the lift.
- There is step free access to the accessible toilet, via lift.

Features and Dimensions

Collapse -

- This is a shared toilet.
- A key is not required for the accessible toilet.
- There is pictorial signage on or near the toilet door.
- The door opens outwards.
- The door is heavy.
- The door is locked by a twist lock.
- The width of the accessible toilet door is 86cm (2ft 10in).
- The dimensions of the accessible toilet are 165cm x 175cm (5ft 5in x 5ft 9in).
- The accessible toilet does not have an unobstructed minimum turning space of 150cm x 150cm.
- The toilet has a non slip floor.
- There is a lateral transfer space.
- As you face the toilet pan the transfer space is on the right.
- The lateral transfer space is 90cm (2ft 11in).
- There is a flush on the transfer side.
- There is not a spatula type lever flush.
- There is a dropdown rail on the transfer side.
- There is an emergency alarm.
- The emergency pull cord alarm is fully functional.
- There is not a flashing fire alarm beacon within the toilet.
- Disposal facilities are available in the toilet.
- There is a/are female sanitary and open waste paper bin disposal units.
- There is a/are coat hook(s).
- There are coat hooks in the toilet at 120cm and 180cm from the floor.

Position of Fixtures

Collapse -

- There is a/are wall-mounted grab rail(s) available.
- As you face the toilet the wall-mounted grab rail(s) is/are on the left.
- There is not a vertical wall-mounted grab rail on the transfer side.
- There is a horizontal wall-mounted grab rail on the opposite side of the seat to the transfer space.
- There is a mirror.
- The mirror is not placed at a lower level or at an angle for ease of use.
- There is a shelf next to the toilet.
- The shelf is not between 90cm and 100cm.

Cookie Policy ed cistern.





- The height of the toilet seat above floor level is 40cm (1ft 4in).
- There is a toilet roll holder.
- The toilet roll holder can be reached from seated on the toilet.
- The toilet roll holder is not placed higher than 100cm (3ft 3in).
- There is a wash basin.
- The wash basin cannot be reached from seated on the toilet.
- The wash basin is placed higher than 74cm (2ft 5in).
- The height of the wash basin is 80cm (2ft 7in).
- There is a vertical wall-mounted grab rail on the right hand side of the wash basin.
- The wash basin tap type is lever.
- There is not a mixer tap.
- There is a soap dispenser.
- The soap dispenser cannot be reached from seated on the toilet.
- The height of the soap dispenser is 90cm.
- There is a towel dispenser.
- The towel dispenser cannot be reached from seated on the toilet.
- The towel dispenser is not placed higher than 100cm (3ft 3in).
- The height of the towel dispenser is 140cm (4ft 7in).
- There is not a hand dryer.

Colour Contrast and Lighting

Collapse -

- The contrast between the external door and wall is good.
- The contrast between the internal door and wall is poor.
- The contrast between the dropdown rail(s) and wall is poor.
- The contrast between the wall-mounted grab rail(s) and wall is poor.
- The toilet seat colour contrast is poor.
- The contrast between the walls and floor is good.
- The lighting levels are good.

Baby Changing Facilities

Collapse -

- Baby changing facilities are located within the accessible toilet.
- The baby change table is not set against the wall, permanently fixed at 75cm from the floor.
- The baby change table is not height adjustable.
- The height of the baby change table once extended is 93cm (3ft 1in).

• Standard toilet facilities are available.

Access to Standard Female and Male Toilet(s) Collapse -

- The female and male toilet facilities that were surveyed are located on the ground floor and mezzanine floor.
- There is step free access to the female and male toilet(s).
- There is pictorial signage on or near the toilet door.
- An ambulant toilet with wall-mounted grab rails is not available.
- The wash basin tap type is lever.
- There is not a flashing fire alarm beacon within the toilets.
- Lighting levels are good.





Who we are...

Homepage About Us Access Icons FAQs Contact Us Press and Media

The way we work...

Website Conditions
Acceptable Use Policy
Cookie Policy
Privacy Policy
Accessibility Policy
Common Access Guide Terms Explained

Our support for business

Disabled Charities and Useful Links FAQs Around Our Surveyors

Follow @DisabledGo

Join us...





Google+
Switch to mobile site











eCommerce Solutions by PureNet